


JOHN B. STORER, P.E.  
Director Community Services  
j.storer@dover.nh.gov

RAYMOND VERMETTE JR.  
Facility Supervisor  
r.vermette@dover.nh.gov

ARNOLD POWERS  
Laboratory Supervisor  
a.powers@dover.nh.gov



484 Middle Road  
Dover, New Hampshire 03820-4932  
(603) 516-6475  
Fax: (603) 516-6477  
www.dover.nh.gov

## City of Dover, New Hampshire

COMMUNITY SERVICES DEPARTMENT  
WASTEWATER TREATMENT FACILITY  
INDUSTRIAL PRETREATMENT  
A DIVISION OF WASTEWATER TREATMENT  
FOR THE CITY OF DOVER

John Wong  
Owner Asia  
42 Third St.  
Dover, NH 03820

01/03/22

### NOTICE OF VIOLATION

In the matter of Asia's discharge to the sanitary sewer there were three areas identified as issues during the City's Pretreatment inspection on 12/28/2021. **The first is the oily solids from the grease trap on the wall, floor, and furnace pit in the cellar. The second is the open sump pump pumping grease and water, and third the old, rusted, leaking grease trap.** These conditions indicate violations of Dover's Sewer Use Ordinance have occurred.

These findings are made and notice issued pursuant to the authority vested in the City Manager under section 121-11 of the City's Sewer Use Ordinance.

One or more of the numerical limits or requirements indicated in Asia's discharge permit #1214 were exceeded as follows:

**Failure to replace broken and nonfunctioning grease trap.  
Failure to maintain trap creating unsanitary conditions in the restaurant's cellar. Discharging oil/grease water from sump pump.**

Observed	Local	Federal
<u>Concentration</u>	<u>Uniform Conc. Limit</u>	<u>DailyMax./MonthlyAvg.</u>

### NOTICE

These violations alone or along with future violations may subject Asia to **Significant Noncompliance (SNC)**.

**Therefore**, based on the above findings, Asia is hereby notified that:

1) It is in violation of its discharge permit and the Sewer Use Ordinance of the City of Dover.

2a) It must clean the oily solids in the cellar by 1/5/22.

b) It must install a functioning grease trap by 1/22/22.

c) It must cease from discharging oil/grease from its sump.

3) It must explain the cause of these violations.

4) It must explain what will be done to prevent these violations in the future.

Signed:

James Casey  
Pretreatment Coordinator

DEC. 1/3/22

PICKED UP  
WHILE I  
WAS THERE

Notice of Violation  
Receipt


Answer questions #3 & #4 above on lines below

- (3) The problem was going to be fixed but Paul Hayes, the plumber broke the contract and left with our money so we had to go to court -
- (4) Once a week cleaning for prevention + docu.

Asia received this Notice of Violation (NOV) for failure to maintain a properly functioning grease interceptor, pumping oil/grease from sump pump, and for non-sanitary conditions created in cellar from failed grease interceptor.

The NOV was dated 01/03/22.

SIGNED,

  
John Wong

Please Return this receipt signed by 01/10/22 to:

Dover Wastewater Treatment Plant  
484 Middle Rd  
Dover, NH 03820  
Attn: Pretreatment

- STIPULATION - The milestone time frames included in this (NOV) can be overridden by Dover's Building Inspection Department as there are other issues associated with Asia Restaurant that might require more expeditious correction times and actions.